








Map 4 Soil On-site Septic Capability Westford Vermont

Legend

On-Site Septic Suitability by Soil Type*

-  Not Suited or Not Rated
-  Marginally Suited
-  Moderately Suited
-  Well Suited
-  Stream Centerline
-  Water Body
-  2008 Parcel Data



1:48,000

1 inch = 4,000 feet

0 1,500 3,000 6,000 Feet

0 0.5 1 2 Miles

NOTE: Soils data are generalized.
An on-site investigation is required for a definitive analysis of septic suitability.

Sources:
Roads - e911 road data, last updated July 2014
Parcels - 2008 - Updated by IVS
Surface water - VT Hydrography set - 2010
Septic soils - NRCS - 2005

Disclaimer:
The accuracy of information presented is determined by its sources. Errors and omissions may exist. The Chittenden County Regional Planning Commission is not responsible for these. Questions of on-the-ground location can be resolved by site inspections and/or surveys by registered surveyor. This map is not sufficient for delineation of features on-the-ground. This map identifies the presence of features, and may indicate relationships between features, but is not a replacement for surveyed information or engineering studies.

