


# Map 4 Soil On-site Septic Capability Westford Vermont

## Legend

### On-Site Septic Suitability by Soil Type

- Well Suited
- Moderately Suited
- Marginally Suited
- Not Suited or Not Rated
- Stream Centerline
- Water Body
- 2017 Parcel Data



NOTE: Soils data are generalized.  
An on-site investigation is required for a definitive analysis of septic suitability.

Sources:  
Roads - VTrans - downloaded Feb. 2020  
Parcels - 2017  
Surface water - VT Hydrography set - 2010  
Septic soils - NRCS - 2005

Disclaimer:  
The accuracy of information presented is determined by its sources. Errors and omissions may exist. The Chittenden County Regional Planning Commission is not responsible for these. Questions of on-the-ground location can be resolved by site inspections and/or surveys by registered surveyor. This map is not sufficient for delineation of features on-the-ground. This map identifies the presence of features, and may indicate relationships between features, but is not a replacement for surveyed information or engineering studies.

